

2 ON DESK + 4 UNDER DESK

Connection guide

P-Pack power bundle | DRD-BUN2O4U

1 MAINS SUPPLY



3m starter lead

13A UK plug to GST18 female
Connects to the under-desk input.

2 UNDER-DESK POWER



P-PACK 4G

4 UK sockets, individually fused at 5A
GST18 output feeds the desktop unit.

3 DESKTOP POWER



P-PACK desktop unit

2 UK sockets + dual USB + master switch
500mm drop lead with male GST18.

ONE SUPPLY. SIX UK SOCKETS. DESKTOP USB CHARGING.

The desktop drop lead plugs directly into the under-desk unit. No splitter is required.

Connect all components before plugging into the wall. Follow the supplied installation instructions.

All sockets share one 13A supply. Allow cable slack for routing and desk movement. Schematic only; not to scale.