3 ON DESK + 3 UNDER DESK

Connection guide

DRD-BUN3ON3UN

1 MAINS SUPPLY



3m starter lead

UK plug to female 3-pole connector

Connects to the under-desk input.

2 UNDER-DESK POWER



P-PACK 3G

3 individually fused UK sockets

Output feeds the desktop unit.

3 DESKTOP POWER



MAXI DESK 3/U

3 UK sockets + dual USB + master switch

500mm drop lead with male GST18.

ONE SUPPLY. SIX UK SOCKETS. DESKTOP USB CHARGING.

The desktop lead connects directly to the under-desk output. No splitter is required.

Connect all components before plugging into the wall. Follow the supplied installation instructions.

All outlets share one supply. Observe all component ratings and allow cable slack. Schematic only; not to scale.

0800 852 1010 | info@dataroomdirect.com | www.dataroomdirect.com