

4 ON DESK + 2 UNDER DESK

Connection guide

DRD-BUN2O4U-1

1 MAINS SUPPLY



3m starter lead

UK plug to female 3-pole connector
Connects to the under-desk input.

2 UNDER-DESK POWER



P-PACK 2G

2 individually fused UK sockets
Output feeds the desktop unit.

3 DESKTOP POWER



P-PACK desktop unit

4 UK sockets + dual USB + master switch
500mm drop lead with male GST18.

ONE SUPPLY. SIX UK SOCKETS. DESKTOP USB CHARGING.

The desktop lead connects directly to the under-desk output. No splitter is required.

Connect all components before plugging into the wall. Follow the supplied installation instructions.

All outlets share one supply. Observe all component ratings and allow cable slack. Schematic only; not to scale.