GROMMET + 4 UNDER DESK

Connection guide

DRD-BUN4GROMUSB

1 MAINS SUPPLY



3m starter lead

UK plug to female 3-pole connector

Connects to the under-desk input.

2 UNDER-DESK POWER



P-PACK 4G

4 UK sockets, individually fused at 5A

Output feeds the desktop unit.

3 DESKTOP POWER



Desk power grommet

1 UK socket + USB-A/C charging

500mm connecting lead to GST18.

IN-DESK POWER AND USB. FOUR EXTRA SOCKETS BELOW.

The grommet lead connects to the under-desk output. Black or white finish as selected.

Connect all components before plugging into the wall. Follow the supplied installation instructions.

All outlets share one supply. Observe all component ratings and allow cable slack. Schematic only; not to scale.

0800 852 1010 | info@dataroomdirect.com | www.dataroomdirect.com